

NTSB Identification: NYC75AN087

14 CFR Part 135 Scheduled operation of PROVINCETOWN B
 Aircraft: BRITTNORMAN BN-2A, registration: N90PB

FILE	DATE	LOCATION	AIRCRAFT DATA	INJURIES F S M/N	FLIGHT PURPOSE	PILOT DATA
3-0027	75/2/23 TIME - 1935	PROVINCETOWN,MA	BRITTNORMAN BN-2A N90PB DAMAGE-SUBSTANTIAL	CR- 0 0 1 PX- 0 0 1 OT- 0 0 0	COMMERCIAL COMMUTER AIR CARRIER AIR TAXI-PASSG S-D	COMMERCIAL, AGE 30, 3600 TOTAL HOURS, 310 IN TYPE, INSTRUMENT RATED.
NAME OF AIRPORT - PROVINCETOWN MUNI		DEPARTURE POINT BOSTON,MA		INTENDED DESTINATION PROVINCETOWN,MA		
TYPE OF ACCIDENT COLLISION WITH GROUND/WATER: UNCONTROLLED		PROBABLE CAUSE(S) PILOT IN COMMAND - SPATIAL DISORIENTATION		PHASE OF OPERATION LANDING: FINAL APPROACH		
FACTOR(S) WEATHER - FOG AIRPORTS/AIRWAYS/FACILITIES - AIRPORT FACILITIES: APPROACH LIGHTING		WEATHER BRIEFING - SELF-HELP,PILOT CHECKED WEATHER DATA WEATHER FORECAST - UNKNOWN/NOT REPORTED		SKY CONDITION SCATTERED		CEILING AT ACCIDENT SITE 11000
VISIBILITY AT ACCIDENT SITE 3 MILES OR LESS		OBSTRUCTIONS TO VISION AT ACCIDENT SITE GROUND FOG		PRECIPITATION AT ACCIDENT SITE NONE		TEMPERATURE-F 44
WIND VELOCITY-KNOTS CALM		TYPE OF FLIGHT PLAN NONE		TYPE OF WEATHER CONDITIONS VFR		
REMARKS- ENCRD PTCHY GNDFG.PLT RPRTD DISORIENTING EFFECT,FLASHING RAIL.NO REIL.AC 150/5340-14B APPLIES.						

Full narrative is not available